



Dart Aerospace Ltd.  
1270 Aberdeen St  
Hawkesbury, ON  
K6A 1K7  
Canada

Tel (613) 632-5200  
Fax 613 632-5246

## ENGINEERING CHANGE REQUEST

### ECR 457

<b>Date Opened:</b>	11/2/22 12:08 PM	<b>Requested By:</b>	Drouin, Steven
<b>Type:</b>	Drawing/Pattern Change	<b>Requester*:</b>	Bellavance, Marc
<b>Priority:</b>	Medium	<b>DE Approver*:</b>	Shepherd, David
<b>Status:</b>	Quality Disposition	<b>ECR Lead*:</b>	Drouin, Steven
<b>Reason:</b>			
<b>Expense:</b>	0		
<b>Target Date:</b>			
<b>Execution Date:</b>			
<b>ECR Approval No:</b>			
<b>RE (R&amp;D):</b>		<b>**BRIEF DESCRIPTION**:</b>	RBW6500G03531-3G
<b>Status Note:</b>		<b>DESCRIPTION/ ADR CONTENT**:</b>	Issue with RBW6500G03531-3G the degree is not correct per a client.

### CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
CWEPA01				

### PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
RBW6500G03531-3G		Under Review	Bearing Outer Race Installation Tool	Finished Good			RBW6500G03531-3G-RevA.pdf
RBW6500G03531-3G-1		Under Review	Press Assembly	Sub-assembly			RBW6500G03531-3G-RevA.pdf
RBW6500G03531-3G-2		Under Review	Press	Sub-assembly			RBW6500G03531-3G-RevA.pdf
RBW6500G03531-3G-3		Under Review	Base	Sub-assembly			RBW6500G03531-3G-RevA.pdf
RBW6500G03531-3G-4		Under Review	Flange Support	Sub-assembly			RBW6500G03531-3G-RevA.pdf
RBW6500G03531-3G-5		Under Review	Centering Pin	Sub-assembly			RBW6500G03531-3G-RevA.pdf

### INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
RBW6500G03531-3G		0 *	0 *	0 Update Jobs only when drawing approved
RBW6500G03531-3G-1		1 Use as is	0 *	0 Update Jobs only when drawing approved
RBW6500G03531-3G-2		0 Quarantine	0 *	0 Cancel All Scheduled Jobs
RBW6500G03531-3G-3		1 Use as is	0 *	0 Cancel All Scheduled Jobs
RBW6500G03531-3G-4		9 Use as is	0 *	0 Update Jobs only when drawing approved
RBW6500G03531-3G-5		1 Use as is	0 *	0 Update Jobs only when drawing approved

### EFFECTS

Effect Group	Effects
1. Quarantine?	Immediate quarantine required (RBW6500G03531-3G-2)
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required (RBW6500G03531-3G-2)
3. ECR Lead Assessment - Status During ECR	Active - No Under Review
4. Production Type	In-house production